

SAFETY RECALL

Salsa Cycles CroMoto S.U.L. Bicycle Stems CroMoto S.U.L. Quill and CroMoto S.U.L. Threadless Stems are affected.



Aftermarket stems sold after: April 1, 2010

**These stems may crack or break,
causing the rider to fall and suffer injuries.**

**Stems may be identified by a hash mark
on the interior clamp portion of the stem body.**

**Contact your local bicycle retailer to arrange inspection
and a free replacement if necessary.**

**For more information, call Quality Bicycle Products at:
(877) 774-6208**

Or visit the website at: www.salsacromotostem.com