

# **SAFETY RECALL**

**Salsa Cycles CroMoto S.U.L. Bicycle Stems**  
CroMoto S.U.L. Quill and CroMoto S.U.L. Threadless Stems are affected.



**Aftermarket stems sold after: April 1, 2010**

**These stems may crack or break,  
causing the rider to fall and suffer injuries.**

**Stems may be identified by a hash mark  
on the interior clamp portion of the stem body.**

**Contact your local bicycle retailer to arrange inspection  
and a free replacement if necessary.**

**For more information, call Quality Bicycle Products at:  
**(877) 774-6208****

**Or visit the website at: [www.salsacromotostem.com](http://www.salsacromotostem.com)**